

From: ["Jones, Jennifer M." <JonesJM@cdmsmith.com>](mailto:JonesJM@cdmsmith.com)
To: ["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)
["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)
CC: ["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott.Coffey@cdmsmith.com)
younghs@cdmsmith.com
Date: 6/30/2018 5:13:59 PM
Subject: 2nd email- Surface sediment oversight 6/30/18
Attachments: [Image-1.png](#)
[Image.png](#)

Hi,

They're finishing up for the day on the Methow. I mentioned in my email this morning that we were in the Upriver reach but we were actually in the Downtown reach today between RM 14.5- 14.9. Four surface sediment samples were collected aboard the Methow. They had some recovery issues at one location and another location had silty sand with <35 % fines. This will be described in the daily report.

Here is a photo of Gravity personnel probing sediments, and another showing kayakers close to the boat. Very busy on the river today.

Thanks,
Jennifer